


**Designers of High** Definition digital video acquisition systems for ROV and diver **IRM** operations

Raymond Ruth

# NET<sub>MC</sub> Marine


### **The Problem**





### **DVCi Solution**





# NET<sub>MC</sub> Marine

### **DVCi Results**




# NETMC Marine

### **Clearer Data – A Comparison**



**Standard Definition** 



#### High Definition DVCi

"Previous reports had not identified the through coating damage to the outer sheathing, which appears to have been there for a while, the coating damage seems obvious from the HD camera images, but had not been spotted previously" NET<sub>MC</sub> Marine











#### **DVCi – Integration**

DVCI SR





